


UNITED STATES



09851819-031001

H.A.T.S. - Patient Information

Reset Caliper Color

Patient Name

Age Gender

Missing Teeth

Malformed Teeth

Doctor or Staff Performing Analysis

NOTE:
If a tooth is malformed or missing, it is recommended that a "zero" be entered into the analysis. The resulting correction necessary will indicate the size of the replacement tooth or teeth necessary to eliminate the discrepancy.

Figure 2A

H.A.T.S. - Patient Information

Reset Caliper Color

Pat

Age Gender

Miss

Malformed Teeth

Doctor or Staff Performing Analysis

NOTE:
If a tooth is malformed or missing, it is recommended that a "zero" be entered into the analysis. The resulting correction necessary will indicate the size of the replacement tooth or teeth necessary to eliminate the discrepancy.

Figure 2B

H.A.T.S.

Reset

Analysis Type

201 ☒ 6 Tooth

202 ☒ 12 Tooth

203 ☒ Input Tooth Sizes

204 ☒ Input Sums

Calculate

Print

UPPER

TOOTH	3	4	5	6	7	8	9	10	11	12	13	14
AVERAGE SIZE	10.40	6.84	7.04	7.91	6.96	8.82	8.82	6.96	7.91	7.04	6.84	10.40
MEASURED SIZE	0	0	0	7.88	5.52	8.72	8.74	5.56	7.86	0	0	0

LOWER

MEASURED SIZE	0	0	0	6.86	5.87	5.36	5.38	5.88	6.84	0	0	0
AVERAGE SIZE	11.14	7.27	7.15	6.93	5.94	5.42	5.42	5.94	6.93	7.15	7.27	11.14
TOOTH	6	5	4	3	2	1	1	2	3	4	5	6
	30	29	28	27	26	25	24	23	22	21	20	19

	Total Anterior	Average	Total Overall	Average
207 <u>Upper Sum</u>	44.28	47.38	0	95.94
<u>Lower Sum</u>	36.19	36.58	0	87.70

208

209

210

<Back

Figure 2C

H.A.T.S. - Analysis Summary

Upper Sum 44.28 ~ 213

Lower Sum 36.19 ~ 214

Recommended Correction:

Increase upper tooth structure by 2.6 mm ~ 215

Reduce lower tooth structure by 2.01 mm ~ 216

GAC Patient Specific Arch Size: SMALL ~ 217

Figure 2D




FIGURE 3




FIGURE 4